

EVACUATION ROUTE

Municipality of Loíza, Puerto Rico

Appendix 2. Video of January 7, 2020, Earthquake Evacuation Process



On January 7, 2020, an earthquake occurred in southwestern Puerto Rico with a 6.4 Mw mainshock. Residents of the town of Loíza left the area concerned about the possibility of a tsunami. The evacuation process was slow and disorganized. It took the resident 80 minutes to travel from the Suárez Parcels to the assembly site at The Outlet 66 Mall. It took 66 minutes to leave the area identified as susceptible to tsunami. To see videos taken by resident during the evacuation process, click the link to [Video 1](#) and [Video 2](#).

A diagram prepared by PRHTA showing the evacuation process that a resident of Parcelas Suárez (a neighborhood in the Loíza town) experienced see the figure attached.

EVACUATION ROUTE

Municipality of Loíza, Puerto Rico

Appendix 2. Video of January 7, 2020, Earthquake Evacuation Process



TIME SPENT ON THE EVACUATION ROUTE
 FROM PR-187 VILLA KENNEDY COMMUNITY
 TO INTERSECTION PR-3 WITH PR-188
 OUTLET 66 MALL, CANOANAS



AERIAL PHOTO
 YEAR OF PHOTO: 2010
 SCALE: 1:15,000

PREPARED BY: PORTAL ENVIRONMENTAL SERVICES OFFICE; JOB DATE: JANUARY, 2020 BY: JH1